
FOREST CITY REGIONAL SCHOOL DISTRICT

FACILITY PLANNING STUDY 2024




PART A: EXISTING CONDITIONS



FOREST CITY REGIONAL SCHOOL DISTRICT

PHASES OF CONSTRUCTION FOREST CITY, PENNYSLVANIA






FOREST CITY REGIONAL SCHOOL DISTRICT

PHASES OF RENOVATION FOREST CITY, PENNYSLVANIA





FOREST CITY REGIONAL SCHOOL DISTRICT

DIVISION OF THE SCHOOL DISTRICT FOREST CITY, PENNYSLVANIA



PART B: BUILDING EVALUATION

IMPROVEMENTS SUMMARY Forest City Regional School District



September 10, 2024

FINAL

Summary Recommendations and Cost							
Building	Anticip	Anticipated Replacement					
Dunuing	Short Term Mid Term Lor		Long Term	Total			
Site / Paving	\$375,000	\$275,000	\$475,000	\$1,125,000			
Forest City Regional Elementary School	\$1,126,700	\$278,750	\$396,750	\$1,802,200			
Forest City Regional High School	\$1,296,300	\$1,341,750	\$844,750	\$3,482,800			
SUBTOTAL	\$2,423,000	\$1,620,500	\$1,241,500	\$6,410,000			
	4%	8%	12%				
Escalation	\$96,920	\$129,640	\$148,980	\$375,540			
Subtotal	\$2,519,920	\$1,750,140	\$1,390,480	\$6,785,540			
Soft Costs 12%	\$302,390	\$210,017	\$166,858	\$679,265			
TOTAL	\$2,822,310	\$1,960,157	\$1,557,338	\$7,464,805			

(The soft cost percentage includes Architectural and Engineering fees at 8.5% and 3.5% for other project related costs as necessary)

Site (FCRSD)

Forest City Regional School District



September 10, 2024					
Recommendations and Cost					
Evaluated System	Anticipa	ted Repla	acement	Detailed Information	
System / Subsystem Component	Short Term	Mid Term	Long Term	Comments	
Site Construction					
Administration Parking Lot					
Base Repair (Base Course/2A) - 20% of Area Mill and Resurface - Entire Area Concrete Sidewalk Replacement including Gravel Subbase Stair Repairs & Center Handrails on Exterior Stairs	\$290,000				
Elementary Parking Lot Spot Base Repairs & Seal Coat	\$20,000				
Remove & Replace Pavement at Driveway Entrance Regrade & Stabilize Swale on East Side of Drive	\$15,000				
Elementary Playground Handicap Access Walk	\$50,000				
40 Car Expansion of High School Parking Lot & Improved Circulation, Seal Coat Existing Lot Clearing, Grading, Paving, Sealcoating & Storm Drainage			\$280,000		
Soccer / Softball Field					
Regrading & Drainage Improvements, Topsoil & Seeding		\$200,000			
Bleachers Handicap Parking & Improved Access Walk		\$50,000 \$25,000			
Baseball Field					
Drainage Improvements Fine Grade & Pave Parking Lot			\$80,000 \$115,000		
Site Total	\$375,000	\$275,000	\$475,000	\$1,125,000	

Forest City Regional Elementary School (FCRES)

Forest City Regional School District

DUA archi

September 10, 2024							
Recommendations and Cost							
Evalu	Anticipa	ated Repla	acement	Detailed Information			
System / Subsystem	Component	Short Term	Mid Term	Long Term	Comments		
General Construction							
Interior							
	Classroom 504 - French Drain Gym	\$15,000		\$200,000	Water Damage Replace bleachers (insurance?)		
	(2) Courtyards A & B			\$75,000	Courtyard upgrade cost will vary depending on the number of courtyards improved and the level of the improvements. The extent of pavement / hard surface, landscaping, furniture and shade structures will determine the final costs. The cost range is projected at \$40,000 to \$150,000. We included \$75,000 in the cost		
	Cosmetic upgrade to classrooms			\$50,000	The Classrooms are well maintained and for the most part in good condition. There are some minor finish work and casework that should be repaired but they do not require a full upgrade. A full upgrade would include new floor, wall and ceiling finishes. Also, with the ceiling new LED lighting would be installed. The cost included in the summary is intended to cover the minimal scope. Full scope would be in the \$25,000 per classroom		
	Cosmetic upgrade to corridors			\$35,000	Similar to the classrooms, the corridors are well maintained. Minimal work is projected and included in the report.		
Exterior							
	Metal panel Exterior masonry repair		\$20,000	\$25,000	Refinish rusted metal panels Repair deteriorating mortar and brick		
FCRES Subtotal		\$15,000	\$20,000	\$385,000	\$420,000		
FCRES MEP Subtotal		\$1,111,700		\$11,750	 		
FCRES Total		\$1,126,700	\$298,750	\$396,750	\$1,822,200		

Forest City Regional Elementary School (FCRES)

Forest City Regional School District




		Se	ptember 10, 20	24	architecture + design		
Recommendations and Cost							
Evaluated Syst	Anticipa	ated Repla	acement	Detailed Information			
System / Subsystem (Component	Short Term	Mid Term	Long Term	Comments		
Mechanical Const.							
HVAC Add Air	conditioning	\$700,000			Add AC to all instructional rooms that do not currently have it (phased approach). Increase comfort for students and faculty year round. (Note: Will likely require electrical		
Automat	Building ion System (BAS) - Equipment	\$363,500			Current system includes old outdated controllers on a dedicated LAN. Replace outdated equipment (phased approach over next three summers) and migrate system to main LAN. Will provide increased functionality,		
Automat	Building ion System (BAS) - 6 Equipment		\$253,000		Current system includes newer but discontinued controllers on a dedicated LAN. Replace outdated equipment and migrate system to main LAN. Will		
Plumbing Const.							
N/A							
Electrical Const.							
Power							
Faculty I	Break Room 405			\$3,000	Additional receptacles/circuits needed for microwaves an		
Panelboa	rd - Corridor C-4	\$6,000			An existing Westinghouse panel located in the corridor is missing it's lockable cover, and is currently covered in plywood. Replacement is recommended. (1 panel)		
Panelboa	rds - Cooler C-5.2		\$12,000		GPI found several panelboards throughout the building that are original Westinghouse panels. Due to age, parts are becoming scarce. Replacement is recommended. (2		
Mechani	cal Systems Power	\$42,200			Additional power/electrical infrastructure will be required to support adding air conditioning to spaces without AC. Includes (2)-480V, 3 Phase. 225Amp panelboards with		
Security							
Security	Cameras (existing)		\$13,750		Existing Vicon security cameras are nearing their end of life. Currently they are 6-7 years old and coming out of supported life. Existing cabling can remain and be reused Approximately 110 cameras throughout entire building.		
Security	Cameras (new)			\$8,750	Some areas need additional security cameras. It was noted approximately 10 additional cameras would cover deficient areas throughout the entire building. This cost includes 5 cameras with 150ft of CAT6 cable terminated		
FCRES MEP Subtotal		\$1,111,700	\$278,750	\$11,750	\$1,402,20		

Forest City Regional High School (FCRHS)

Forest City Regional School District September 10, 2024



Recommendations and Cost						
Evalua	Anticipated Replacement					
System / Subsystem	Component	Short Term	Mid Term	Long Term	Comments	
General Construction						
Interio	· Auditorium		\$600,000		Front curtain track, projector screen, house & theatrical lighting, water damage / leaking below grade along plan	
	Control Room		\$4,000		Replace flooring	
	Drama Storage			\$10,000	Replace ACT	
	Cafeteria	\$1,500			Replace missing & damaged vinyl wall base, Ala Carte underutilized	
	Kitchen		\$250,000		Dishwasher & Steamers function but is past useful lifespan, replace missing and damaged wall base	
	Locker Pooms / Toilet Pooms		\$75,000		Address tile failure issue	
	Locker Rooms / Toilet Rooms (2) Courtyards C & D		Ψ13,000	\$75,000	Courtyard upgrade cost will vary depending on the number of courtyards improved and the level of the improvements. The extent of pavement / hard surface, landscaping, furniture and shade structures will determine the final costs. The cost range is projected at \$40,000 to \$150,000. We included \$75,000 in the cost	
	Library -121			\$200,000	The vision for the library is to create a new modern space that promotes learning and digital opportunities for the students. Work areas will vary from individual to small / mid size groups. In addition the space could be configured for faculty instruction and board meetings. Costs will vary based on final design and technology included. Budget number included will vary	
	Classroom 213		\$10,000		Replace flooring	
	Gym 100		Ψ10,000	\$125,000	Basket height adjustment, includes replacement.	
	Classroom 206 (former FCS)			\$75,000	More efficient storage	
	Vestibule B-8 Entry doors are too small		\$40,000		Principal noted the door is used for building loading and unloading.	
	Cosmetic upgrade to classrooms			\$70,000	The Classrooms are well maintained and for the most part, in good condition. There are some minor finish work and casework that should be repaired but they do not require a full upgrade. A full upgrade would include new floor, wall and ceiling finishes. Also, with the ceiling new LED lighting would be installed. The cost included in the summary is intended to cover the minimal scope. Full scope would be in the \$25,000 per	
	Cosmetic upgrade to corridors			\$30,000	Similar to the classrooms, the corridors are well maintained. Minimal work is projected and included in	
Exterior			\$20,000			
	Exterior masonry repairs Exterior auditorium wall		\$8,000		Efflorescence - water leaking into auditorium?	
	Vestibule 222.5		\$5,000		Rusted railing	
	Vestibule 222.5		\$10,000		Cracked concrete	
FCRHS Subtotal		\$1,500	\$1,022,000	\$585,000	\$1,608,500	
FCRHS MEP Subtotal	\$1,294,800		\$259,750	` ' ' '		
FCRHS Total	\$1,296,300		\$844,750	. , , ,		



Forest City Regional High School (FCRHS)

Forest City Regional School District



Upgrade Building Automation System (BAS) - Pt 2016 Equipment Upgrade Building Automation System (BAS) - Pt 2016 Equipment Upgrade Building Automation Upgrade Building Automation System (BAS) - Pt 2016 Equipment Upgrade Building Automation System (BAS) - Pt 2016 Equipment Upgrade Building Automation System (BAS) - Pt 2016 Equipment Upgrade Building Automation System (BAS) - Pt 2016 Equipment Upgrade Building Automation System (BAS) - Pt 2016 Equipment Upgrade Building Automation System (BAS) - Pt 2016 Equipment Add Exhaust Fan in 108.2 System (BAS) - Pt 2016 Equipment Add Exhaust Fan in 108.2 System (BAS) - Pt 2016 Equipment Add Exhaust Fan in 108.2 System (BAS) - Pt 2016 Experiment (BAS)					D	1 4 1 C 4		
System / Subsystem Component Form Comments					Recom	imendations and Cost		
System Component Compone	Evaluated System		Anticipated Replacement			Detailed Information		
HVAC Add AC to Aceta Without Comment Comm	System / Subsystem	Component		Mid Term	C	Comments		
Upgrade Bailding Automation System (BAS) - Pre 2016 Equipment Upgrade Bailding Automation System (BAS) - Post 2016 Equipment Upgrade Bailding Automation System (BAS) - Post 2016 Equipment Upgrade Bailding Automation System (BAS) - Post 2016 Equipment Upgrade Bailding Automation System (BAS) - Post 2016 Equipment Upgrade Bailding Automation System (BAS) - Post 2016 Equipment Upgrade Bailding Automation System (BAS) - Post 2016 Equipment System (BAS) - Post 2016 Equipment System (BAS) - Post 2016 Equipment Add Eshans Fan in 108.2 System (BAS) - Post 2016 Equipment Add Eshans Fan in 108.2 System (BAS) - Post 2016 Equipment The boilers are availing the end of their expected life. Replace for reliability and modest efficiency gains (3-5% reduced on the machine. Insuli a permanent fan and dyets. Plumbing Const. Puerer Classroom 112, 114, 116-118, 20-25, 200 Classroom 112, 114, 116-118, 20-25, 200 Classroom 112, 114, 116-118, 20-25, 207, 200 Panelboards Finness Weight Room 101 Bec Closes Plumbing Sorges 113 System (BAS) - Post 2016 Energency Generator Puerboards Kitchen 315 System (BAS) - Post 2016 Syst	Mechanical Const.							
Cigreate Building Automation System (BAS) - Pre 2016 Sa63,500 three summers) and migrate system includes of understand controllers on a dedicated LAN. Replace controller and maintainability.	HVAC	C Add AC to Areas Without	\$600,000			Add AC to all instructional rooms that do not currently have it (phased approach over next three summers). Increase comfort for students and faculty year round. (Note: Will likely require electrical service upgrades.)		
Ugrade Building Automation System (RAS) - Post 2016 Equipment System (RAS) - Post 2016 Equipment System (RAS) - Post 2016 Equipment System (RAS) - Post 2016 Add Exhaust Fun in 108.2 33.500 The boilers are nearing the end of their expected life. Replace for reliability and maintainability. Employed the laser engraving muchine in industrial arts classroom is using a temporary fan with flexible ducts to exhaust smoke and from the machine. Install a permanent fan and ducts. Plumbing Const. Power Power		System (BAS) - Pre 2016	\$363,500			Current system includes old outdated controllers on a dedicated LAN. Replace outdated equipment (phased approach over next		
Replace Boiles \$340,000 The boilers are nearing the end of their expected life. Replace for reliability and modes efficiency gains (3-5% reduced end from the machine. Install a permanent fan and ducts. Plumbing Const.		Upgrade Building Automation System (BAS) - Post 2016		\$253,000		Current system includes newer but discontinued controllers on a dedicated LAN. Replace outdated equipment and migrate system to main LAN. Will provide increased functionality, reliability and maintainability.		
Domestic Hot Water Replace Water Heater \$25,000 The central storage water heater is nearing the end of its expected. life. Replace for reliability (at the same time as the bolk of the central storage water heater is nearing the end of its expected. life. Replace for reliability (at the same time as the bolk of the central storage water heater is nearing the end of its expected. life. Replace for reliability (at the same time as the bolk of the central storage water heater is nearing the end of its expected. life. Replace for reliability (at the same time as the bolk of the central storage water heater is nearing the end of its expected life. Replace for reliability (at the same time as the bolk of the central storage water heater is nearing the end of its expected life. Replace for reliability (at the same time as the bolk of the central storage water heater is nearing the end of its expected life. Replace for reliability (at the same time as the bolk of the central storage water heater is nearing the end of its expected life. Replace for reliability (at the same time as the bolk of the central storage water heater is nearing the end of its expected life. Replace for reliability (at the same time as the bolk of the central storage water heater is nearing the end of its expected life. Replace for reliability (at the same time as the bolk of the central storage water heater is nearing the end of its expected. If the same time as the bolk of the central storage water heater is nearing the end of its expected. If the same time as the bolk of the central storage water heater is nearing the end of its expected. If the same time as the bolk of the life, and the same time as the bolk of the life, and the same time as the bolk of the life, and the same time as the bolk of the life, and the same time as the bolk of the life, and the life is the control of the equipment. Security Cameras (existing)		Replace Boilers				The boilers are nearing the end of their expected life. Replace for reliability and modest efficiency gains (3-5% reduced energy The laser engraving machine in industrial arts classroom is using a temporary fan with flexible ducts to exhaust smoke and odors from the machine. Install a permanent fan and ducts.		
Electrical Cons. Power Classroom 112, 114, 116-118, 200-205, 207, 209 Panelboards Fitness Weight Room 101 Elec Closet Panelboards Fitness Weight Room 101 Elec Closet Panelboards Strices Replacement is recommended. (2 panels) GPI found several panelboards throughout the building that are original Westinghouse panels. Due to age, parts are becoming scarce, Replacement is recommended. (3 panels) GPI found several panelboards throughout the building that are original to the b	Plumbing Const.							
Power	Domestic Hot Water	Replace Water Heater	\$25,000			The central storage water heater is nearing the end of its expected life. Replace for reliability (at the same time as the boilers).		
Classroom 112, 114, 116-118, 200-205, 207, 209 Panelboards Fitness Weight Room 101 Elec Closet Panelboards Electrons Weight Room 101 Elec Closet Panelboards Storage 113 Panelboards Storage 113 Panelboards Storage 113 S18,000 Panelboards Kitchen 315 Panelboards Kitchen 315 S18,000 Panelboards Kitchen 315 Panelboards Kitchen 315 S18,000 Panelboards Kitchen 315 S18,000 Panelboards Kitchen 315 Panel	Electrical Const.							
200-205, 207, 209 Panelboards Fitness Weight Room 101 Elec Closet Panelboards Storage 113 S18,000 GPI found several panelboards throughout the building that are original Westinghouse panels. Due to age, parts are becomis scarce. Replacement is recommended. (2 panels) GPI found several panelboards throughout the building that are original Westinghouse panels. Due to age, parts are becomis scarce. Replacement is recommended. (3 panels) GPI found several panelboards throughout the building that are original Westinghouse panels. Due to age, parts are becomis scarce. Replacement is recommended. (3 panels) GPI found several panelboards throughout the building that are original Westinghouse panels. Due to age, parts are becomis scarce. Replacement is recommended. (3 panels) GPI found several panelboards throughout the building that are original Westinghouse panels. Due to age, parts are becomis scarce. Replacement is recommended. (3 panels) GPI found several panelboards throughout the building that are original Westinghouse panels. Due to age, parts are becomis scarce. Replacement is recommended. (3 panels) GPI found several panelboards throughout the building that are original Westinghouse panels. Due to age, parts are becomis scarce. Replacement is recommended. (3 panels) GPI found several panelboards throughout the building that are original Westinghouse panels. Due to age, parts are becomis scarce. Replacement of spanels of the open decree. GPI found several panelboards throughout the building that are original Westinghouse panels. Due to age, parts are becomis scarce. Replacement is recommended (3 panels) GPI found several panelboards throughout the building that are original Westinghouse panels. Due to age, parts are becomis scarce. Replacement of spanels GPI found several panelboards throughout the building that are original Westinghouse panels. Due to age, parts are becomis scarce. Replacement is recommended (3 panels) GPI found several panelboards throughout the building that are original Westinghouse panels.	Power	r						
Panelboards Fitness Weight Room 101 Elec Closet Panelboards Storage 113 S18,000 Panelboards Storage 113 S18,000 Panelboards Kirchen 315 Panelboards Kirchen 315 S18,000 Panelboards Kirchen 315 Panelboards Kirchen 315 S18,000 Panelboards Kirchen 315 S18,000 Panelboards Kirchen 315 Panelboards Kirchen 315 S18,000 Panelboards Kirchen 315 Panelboards Kirchen 315 S18,000 Panelboards Kirchen 315 S18,000 Panelboards Kirchen 315 Panelboards Kirchen 315 Panelboards Kirchen 315 Panelboards Kirchen 315 S18,000 Panelboards Kirchen 315 Panelb		· · · · ·			\$26,000	These spaces are original building and have limited quantity of receptacles. It is recommended additional receptacles be installed.		
Scarce. Replacement is recommended. (3 panels) Panelboards Kitchen 315				\$12,000		GPI found several panelboards throughout the building that are original Westinghouse panels. Due to age, parts are becoming		
scarce. Replacement is recommended. (3 panels) Emergency Generator Mechanical Rm 219 Mechanical Systems Power Security Cameras (existing Controls Security Cameras (existing) Security Cameras (new) Security Cameras (ne		Panelboards Storage 113		\$18,000		GPI found several panelboards throughout the building that are original Westinghouse panels. Due to age, parts are becoming scarce. Replacement is recommended. (3 panels)		
Mechanical Rm 219 Space for future equipment. Additional power/electrical infrastructure will be required to support adding air conditioning to spaces without AC. Includes 480V, 3 Phase. 225Amp panelboards with 400ft of 225Amp feeder.		Panelboards Kitchen 315		\$18,000		GPI found several panelboards throughout the building that are original Westinghouse panels. Due to age, parts are becoming scarce. Replacement is recommended. (3 panels)		
Lighting Auditorium Stage Lighting & Security Cameras (existing) Security Cameras (new) Some areas need additional security cameras. It was noted approximately 10 additional cameras would cover deficient areas 480V, 3 Phase. 225Amp panelboards with 400ft of 225Amp feeder. 480V, 3 Phase. 225Amp panelboards with 400ft of 225Amp feeder. 575,000 Existing lighting in auditorium is older incandescent. GPI recommends replacement of existing lighting are incandescent fixtures. It was noted there are issues getting the correct color lamps to come or remain on during a performance. Lighting controls are original to the auditorium. GPI recommends replacement of existing lighting with new LED fixtures and replacement of controls with new digital DMX lighting controls are original to the auditorium. The existing stage lighting controls are older, analog dimmer panels. It was there are issues getting the correct color lamps to come on and remain on during a performance. GPI recommends replacement of controls with new digital DMX lighting controls to match new LED Lighting. Existing Vicon security cameras are nearing their end of life. Currently they are 6-7 years old and coming out of supported Existing cabling can remain and be reused. Approximately 110 cameras throughout entire building. This cost assumes half at this portion of the building. Security Cameras (new) Some areas need additional security cameras. It was noted approximately 10 additional cameras would cover deficient areas		•		\$5,000		The existing emergency generator in Rm 219 has been abandoned in place. GPI recommends removal of the equipment to make space for future equipment.		
Auditorium Seating Lighting Auditorium Stage Lighting & Seating Lighting Controls Auditorium Stage Lighting & Seating Lighting Controls Auditorium Stage Lighting & Seating Lighting Controls Auditorium Stage Lighting & Security Cameras (existing) Security Auditorium Stage Lighting & Security Cameras (new) Security Cameras (new) Security Cameras (new) Security Cameras (new) Existing lighting in auditorium is older incandescent. GPI recommends replacement of existing lighting are incandescent fixtures. It was noted there are issues getting the correct color lamps to come on and remain on during a performance. Lighting controls are original to the auditorium. The existing stage lighting controls are older, analog dimmer panels. It was noted new LED Lighting. Lighting controls are original to the auditorium. The existing stage lighting controls are older, analog dimmer panels. It was noted new LED Lighting. Existing Vicon security cameras are nearing their end of life. Currently they are 6-7 years old and coming out of supported Existing cabling can remain and be reused. Approximately 110 cameras throughout entire building. This cost assumes half a this portion of the building. Some areas need additional security cameras. It was noted approximately 10 additional cameras would cover deficient areas		Mechanical Systems Power	\$62,800			Additional power/electrical infrastructure will be required to support adding air conditioning to spaces without AC. Includes (2)-480V, 3 Phase. 225Amp panelboards with 400ft of 225Amp feeder.		
Auditorium Stage Lighting Auditorium Stage Lighting Security Cameras (existing) Security Cameras (new) Security Cameras (n	Lighting							
s110,000 remain on during a performance. Lighting controls are original to the auditorium. GPI recommends replacement of existing lighting with new LED fixtures and replacement of controls with new digital DMX lighting controls. Lighting controls are original to the auditorium. The existing stage lighting controls are older, analog dimmer panels. It was there are issues getting the correct color lamps to come on and remain on during a performance. GPI recommends replacement of controls with new digital DMX lighting controls are original to the auditorium. The existing stage lighting controls are older, analog dimmer panels. It was there are issues getting the correct color lamps to come on and remain on during a performance. GPI recommends replacement of controls with new digital DMX lighting controls to match new LED Lighting. Security Cameras (existing) \$13,750 Existing Vicon security cameras are nearing their end of life. Currently they are 6-7 years old and coming out of supported Existing cabling can remain and be reused. Approximately 110 cameras throughout entire building. This cost assumes half a this portion of the building. Security Cameras (new) \$313,750 Some areas need additional security cameras. It was noted approximately 10 additional cameras would cover deficient areas		Auditorium Seating Lighting			ふ / つ ししし	Existing lighting in auditorium is older incandescent. GPI recommends replacement of existing lighting with new LED fixtures for energy savings and increased performance.		
Security Cameras (existing) Security Cameras (existing) Security Cameras (new)		Auditorium Stage Lighting				The existing stage lighting are incandescent fixtures. It was noted there are issues getting the correct color lamps to come on and remain on during a performance. Lighting controls are original to the auditorium. GPI recommends replacement of existing lighting with new LED fixtures and replacement of controls with new digital DMX lighting controls.		
Security Cameras (existing) Security Cameras (existing) \$13,750 \$13,750 Existing Vicon security cameras are nearing their end of life. Currently they are 6-7 years old and coming out of supported Existing cabling can remain and be reused. Approximately 110 cameras throughout entire building. This cost assumes half a this portion of the building. Security Cameras (new) Some areas need additional security cameras. It was noted approximately 10 additional cameras would cover deficient areas						Lighting controls are original to the auditorium. The existing stage lighting controls are older, analog dimmer panels. It was noted there are issues getting the correct color lamps to come on and remain on during a performance. GPI recommends replacement of		
\$13,750 Existing cabling can remain and be reused. Approximately 110 cameras throughout entire building. This cost assumes half a this portion of the building. Security Cameras (new) Some areas need additional security cameras. It was noted approximately 10 additional cameras would cover deficient areas	Security	Y						
Security Cameras (new) Security Cameras (new) Some areas need additional security cameras. It was noted approximately 10 additional cameras would cover deficient areas				\$13,750		Existing Vicon security cameras are nearing their end of life. Currently they are 6-7 years old and coming out of supported life. Existing cabling can remain and be reused. Approximately 110 cameras throughout entire building. This cost assumes half are in this portion of the building.		
		Security Cameras (new)			\$8.750	Some areas need additional security cameras. It was noted approximately 10 additional cameras would cover deficient areas		
FCRHS MEP Subtotal \$1,294,800 \$319,750 \$259,750 \$1,50	FCRHS MEP Subtotal		\$1,294,800	\$319,750	\$259,750	\$1,874,30		

PART C: DESIGN CONCEPTS



FOREST CITY REGIONAL SCHOOL DISTRICT

MIDDLE SCHOOL COURTYARD RENOVATION

FOREST CITY, PENNYSLVANIA






FOREST CITY REGIONAL SCHOOL DISTRICT

HIGH SCHOOL COURTYARD RENOVATION

FOREST CITY, PENNYSLVANIA





FOREST CITY REGIONAL SCHOOL DISTRICT

HIGH SCHOOL LIBRARY FOCUS BOOTHS RENOVATION

FOREST CITY, PENNYSLVANIA



